

TECHNICAL DATA

Geocel® TRADE MATE Glazing Putty



TRADE MATE Glazing Putty is ideal for glazing timber and metal frames. It gives excellent adhesion to glass and window frames, painted and varnished wood and metal.

It can be overpainted in 4 hours, and is resistant to rain in 6 hours.

No sanding down is required.

- Developed for glazing timber & metal frames
- Solvent free acrylic - safe & easy to use
- Excellent adhesion to glass and conventional window frames, metal, painted and varnished wood
- Resistant to direct sunlight and temperature changes
- Gives an excellent finish
- For best product performance, paint the putty 4 hours after application
- Not intended for bedding in double glazed units where the putty is in direct contact with the glazing edge seal

This product is intended for face sealing windows and bedding in single glass panes.

Easy to tool.

Uncured material may be washed away with water.

A small amount of water may be used to aid tooling. Please note that over wetting may washout the putty or slow the cure rate.

In external applications it is recommended that the Trade Mate Glazing Putty is painted after four hours of application in order to protect the putty from weathering as it cures.

PACKAGING

Geocel® Trade Mate Nail Power is available in 310ml cartridges packed in boxes of 12.

TECHNICAL DATA

Form	Smooth void free paste
Chemistry	Water based acrylic
Storage Life	24 months when stored at 23°C
Colour	White
Application Temperature	5°C to 40°C
Skin Time	5 to 15 minutes at 23°C and 50% relative humidity
Cure Time	2 mm per 24 hours at 23°C and 50% relative humidity

APPLICATION

- Ensure surfaces are clean, dry and free from grease, dust and loose particles.
- Cut tip of cartridge. Screw nozzle onto cartridge. Cut off end of nozzle at a 45° angle to the required bead width.
- Apply Putty around the glazing rebate to form a bedding for the glass.
- Press the glass firmly into place and retain with glazing pins.
- Apply a continuous bead of putty around the frame and smooth off, with a putty knife if necessary.
- Cut away any excess after use.

LIMITATIONS

- Store in a cool dry place, away from frost.
- Do not apply if rain is imminent.

Important Note: The information contained herein is offered in good faith and is believed to be accurate. However, because conditions and methods of use of our products are beyond our control, this information should not be used in substitution for customer's tests to ensure that Geocel's products are safe, effective and fully satisfactory for the intended end use. Suggestions of use shall not be taken as inducements to infringe any patent.

Geocel's sole warranty is that the product will meet the Geocel sales specifications in effect at the time of shipment.

Your exclusive remedy for breach of such warranty is limited to refund of purchase price or replacement of any product shown to be other than as warranted.

Geocel specifically disclaims any other express or implied warranty of fitness for a particular purpose or merchantability.

Geocel disclaims liability for any incidental or consequential damage.